



POLE MOUNTING

Installation Manual




Components List:

U-shaped Aluminum Bracket




x2

Corner Aluminum Bracket 1




x2

Corner Aluminum Bracket 2




x2

Corner Aluminum Bracket 3
Components




x2

U-bolt components




x4

Hexagon Head Bolt components



x2


Button Head Socket Cap Bolt
components




x8

Installation Steps:


Step1. As shown: Use 2 PCS U-bolt components to securely fasten the U-shaped aluminum bracket to the pole.



Step2. As shown: Use 2 PCS Corner Aluminum Bracket 3 components to attach Corner Aluminum Bracket 1 to the U-shaped aluminum bracket. Do not tighten the nuts yet.




Step3. As shown: Use 2 PCS Hexagon Head Bolt components to attach Corner Aluminum Bracket 2 to Corner Aluminum Bracket 3. Do not tighten the nuts yet.




Installation Steps:

Step4. Use 2 PCS Corner Aluminum Bracket 3 components to attach the U-shaped aluminum bracket to Corner Aluminum Bracket 2. Do not tighten the screws yet; Then use 2 PCS U-bolt components to securely fasten the U-shaped aluminum bracket to the pole.



Step5. Use 4 PCS Button Head Socket Cap Bolt components to securely fasten the solar panel to Corner Aluminum Bracket 1, and then tighten all



Step6. The installation is now complete.

